


HEADLIGHT DIMMER RELAY REPLACEMENT

BEETLE AND KARMANN GHIA 1967-1971

T2 SPLIT 1967-70, T3 1967-1971

RETROFIT 12V CONVERSIONS ON 1966 MODELS

JK Part Number: J10161



N.B. Whilst every attempt is made to ensure that these instructions are as accurate and clear as possible, we cannot be held responsible for misinterpretation of these instructions or for any subsequent accident or damage caused through mis-fitted parts.